

City of Palm Beach Gardens  
Streets/Stormwater Management NPDES Inspection Form  
Catchbasin/Inlet

5

ID:	VINNY	Date:	2.14.2019
Location:	RIVERSIDE TRAIL NORTH CORP		
Receiving Body:	Inspected 17		
Description:	Cleaned 6		
Weather:			
Corrosion:			
Erosion:			
Vegetation:	✓		
Debris:	✓		
Sediments:	✓		
Litter:	✓		
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:			
Department:			
Vicinity inspected for indication of illicit discharges: <input type="checkbox"/>			

City of Palm Beach Gardens  
Streets/Stormwater Management NPDES Inspection Form  
Catchbasin/Inlet

5

ID:	VINNY + TERENCE	Date:	2.12.19
Location:	A1A FROM LIGHTHOUSE TO DONALD ROSS		
Receiving Body:	ALAMANDA BOULEVARD TO A1A		
Description:	Inspected: 77	Inspected: 19	
	Cleaned: 16	Cleaned: 1	

Weather:	
Corrosion:	
Erosion:	
Vegetation:	
Debris:	✓
Sediments:	
Litter:	✓
Oil/Grease:	
Other:	
Condition:	

Comments:	
Recommendations:	

Inspected By:		
Department:		

Vicinity inspected for indication of illicit discharges:

City of Palm Beach Gardens  
Streets/Stormwater Management NPDES Inspection Form  
Catchbasin/Inlet

5

ID:	VINNY	Date:	2/12/19
Location:	FLYBY: TPK.		
Receiving Body:	Inspected: 12		
Description:	Cleaned: 3		
Weather:			
Corrosion:			
Erosion:			
Vegetation:			
Debris:	✓		
Sediments:			
Litter:	✓		
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:			
Department:			
Vicinity inspected for indication of illicit discharges: <input style="width: 50px; height: 15px;" type="text"/>			

City of Palm Beach Gardens  
Streets/Stormwater Management NPDES Inspection Form  
Catchbasin/Inlet

5

ID:	VINNY	Date:	1. 29. 2019
Location:	KYOTO		
Receiving Body:	Inspected 15		
Description:	Cleaned 11		
Weather:			
Corrosion:			
Erosion:			
Vegetation:	✓		
Debris:	✓		
Sediments:	✓		
Litter:	✓		
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:			
Department:			
Vicinity inspected for indication of illicit discharges: <input type="text"/>			

City of Palm Beach Gardens  
**Streets/Stormwater Management NPDES Inspection Form**  
**Catchbasin/Inlet**

5

ID:	VINNY / TERRENCE	Date:	2:12:2019
<del>Location:</del> Receiving Body:	Lilac & SHADY + 117		
Description:	Inspected: 39 Cleaned: 13		

Weather:	
Corrosion:	
Erosion:	
Vegetation:	✓
Debris:	✓
Sediments:	✓
Litter:	✓
Oil/Grease:	
Other:	
Condition:	

Comments:	
Recommendations:	

Inspected By:		
Department:		

Vicinity inspected for indication of illicit discharges: