

Town of Jupiter Inlet Colony Major Outfalls Inventory

Outfall ID	Outfall Location	Latitude	Longitude	Receivin g Waters	Pipe Size	Pipe Material	Add'I Notes
1	PBC ROW Swale	26.95244	-80.076908	Indian River	18"	RCP	
2	103 Lighthous e Drive	26.95048	-80.078186		24"	RCP	
3	87 Lighthous e Drive	26.94623	-80.077452		15"	VCP	
4	75 Lighthous e Drive	26.94556	-80.073628	Jupiter Inlet	21"	PVC	21" CMP pipe with existing dual 8" PVC through seawall
5	Beach Club Parking Lot	26.9454	-80.073157		12"	RCP	