From: Lina Camacho [mailto:lcamacho@engenuitygroup.com]

Sent: Thursday, June 11, 2015 5:05 PM

To: Bull, Michelle

Subject: RE: Village of Palm Springs Year 4 Annual Report RAI

Hello Michelle,

Attached is the response for the additional information request from you on June 4, 2015. Please let me know if you need anything else.

Thanks,

Lina M. Camacho, P.E.Project Engineer
Icamacho@engenuitygroup.com

LISA A. TROPEPE, P.E.



June 11, 2015

Florida Department of Environmental Protection NPDES Stormwater Program 2600 Blair Stone Road MS 3585 Tallahassee, FL 32399-2400

Re: NPDES Year 4, Cycle 3 Annual Report Village of Palm Springs Engenuity Group Project No. 6001.01

Dear Mrs. Bull:

The following information is being submitted on behalf of the Village of Palm Springs in response to the June 4, 2015 email for NPDES Permit No. FLS000018:

Section VII, Part III.A.9.c

 Did not report training for site plan reviewer. Explain why no training was performed.

The number site plan reviewers should be 1. The site plan reviews inspectors from the Village are certified through The Florida Stormwater, Erosion, and Sedimentation Control Inspector Training program every year.

If you should have any questions please do not hesitate to call.

Sincerely,

Lina Camacho, P.E.

Project Engineer

Cc: John Rouse Lisa Tropepe