


Main Inspections Pipe Run with Images

Project name: City of Lake Park	Mainline ID: CB2-CB1	City: West Palm Beach	Street: Near 530 W Kalmia Dr
Start date/time: 5/16/2019 8:15 AM	Direction: D	Weather: 1	Location code: C
Shape: C	Material: RCP	Height: 15 in.	Width: 15 in.



Weather:

1




Some observations have distance greater than the pipe length

Weather:


1

Stopped at 36.9 ft. with flow
on 5/16/2019 8:39:46 AM

↓ At 36.9 ft. 12/12
ID - Infil Dropper
Rating: **3**
Category: O&M



↓ At 36.9 ft. 1/
CL - Crack Longitudinal
Rating: **2**
Category: Structural



↓ At 36.9 ft.
ACB - Catch Basin
Comments: end video

