

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

ID:	VINNY + SAAWN	Date:	1.28.2019
Location:	JOG RD. (PGA TO DONALD ROSS + MICASO 2 PARK)		
Receiving Body:	# Inspected 81		
Description:	Cleaned 27		
Weather:			
Corrosion:			
Erosion:			
Vegetation:	✓		
Debris:	✓		
Sediments:			
Litter:			
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:			
Department:			
Vicinity inspected for indication of illicit discharges: <input type="checkbox"/>			

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

ID:	VINNY / SHAWN FERRENCE	Date:	1. 24. 2019
Location:	GARDENS → VALENCIA		
Receiving Body:	Inspected 62		
Description:	Cleaned 41		
Weather:			
Corrosion:			
Erosion:			
Vegetation:	✓		
Debris:	✓		
Sediments:			
Litter:			
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:	<input type="text"/>		
Department:	<input type="text"/>		
Vicinity inspected for indication of illicit discharges: <input type="text"/>			

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

ID:	VINNY / SHAWN / TERRENCE	Date:	1.24.2019
Location:	PLANT → LILAC		
Receiving Body:	Inspected 4		
Description:	Cleaned 1		
Weather:			
Corrosion:			
Erosion:			
Vegetation:	✓		
Debris:			
Sediments:			
Litter:			
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:			
Department:			
Vicinity inspected for indication of illicit discharges: <input style="width: 50px;" type="text"/>			

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

ID:	VINNY/STAWN FERRACE	Date:	1.24.2019
Location:	Alamanda		
Receiving Body:	Dispatched to inspect: 2		
Description:	Cleaned 1		
Weather:			
Corrosion:			
Erosion:			
Vegetation:	✓		
Debris:			
Sediments:			
Litter:			
Oil/Grease:			
Other:			
Condition:			
Comments:			
Recommendations:			
Inspected By:			
Department:			
Vicinity inspected for indication of illicit discharges: <input style="width: 50px;" type="text"/>			

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

ID:	VINNY + SHAWN	Date:	1. 28. 2019
Location:	VALENCIA → GARDENS ^{6/11} + 52/6		
Receiving Body:	Inspected 72 LIT LIT		
Description:	Cleaned 38 LIT LIT		

Weather:	
Corrosion:	
Erosion:	
Vegetation:	✓
Debris:	✓
Sediments:	✓
Litter:	
Oil/Grease:	
Other:	
Condition:	

Comments:	
Recommendations:	

Inspected By:	<input style="width: 95%;" type="text"/>	
Department:	<input style="width: 95%;" type="text"/>	

Vicinity inspected for indication of illicit discharges:

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

ID:	VINNY + SHAWN	Date:	1.28.2019
Location:	ALAMANDA → BURNS RD. (A1A → A1A)		
Receiving Body:	Inspected 19		
Description:	Cleaned 3		

Weather:	
Corrosion:	
Erosion:	
Vegetation:	✓
Debris:	✓
Sediments:	✓
Litter:	
Oil/Grease:	
Other:	
Condition:	

Comments:	- Pipe to Retention is clogged
Recommendations:	- Blow out w/ pressure cleaner

Inspected By:	<input type="text"/>	
Department:	<input type="text"/>	

Vicinity inspected for indication of illicit discharges: