

ACTIVITY RECORD

Date: 2-27- 2020 Disaster Name/No.: _____

Location: Valencia Gardens Supervisor: Kac

Work Performed: Cleaned Basins of Leaves + Debris (x14)

For debris collection, must complete the following:

Address: 11770 Valencia to 11900 Valencia Gardens
(Number) (St. Name) (Number) (St. Name)

| LABOR | | | |
|------------------|-------------------------|-------------|-------------|
| Name | Job Title | Time In | Time Out |
| <u>Demetrius</u> | <u>Maintenance Tech</u> | <u>7:00</u> | <u>2:30</u> |
| <u>Dave</u> | <u>Day Laborer</u> | <u>7:00</u> | <u>3:30</u> |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| EQUIPMENT | | | |
|---|----------------|-------------|---|
| Description <small>(Size, capacity, HP, make, model, etc.)</small> | Beginning Time | Ending Time | Leasing Co. <small>(If applicable)</small> |
| <u>Back Pack Blower</u> | | | |
| <u>Shovel</u> | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| MATERIALS | | | |
|---------------------------|----------|------------|---------------------|
| Description | Qty. | Unit Price | In stock or Invoice |
| <u>Trash Bags (Large)</u> | <u>8</u> | | |
| | | | |
| | | | |
| | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|---|---|-------|-----------|
| ID: | | Date: | 2/27/2020 |
| Location: | East Park Dr. from PGA Blvd, to Northwood | | |
| Receiving Body: | Palm Beach | | |
| Description: | Cleaning storm basins at Northwood | | |
| Weather: | Sunny / cloudy | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves debris | | |
| Debris: | | | |
| Sediments: | | | |
| Litter: | Paper | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | | | |
| Comments: | Cleared debris from basins (8) | | |
| Recommendations: | | | |
| Inspected By: | Shawn - Made | | |
| Department: | | | |
| Vicinity inspected for indication of illicit discharges: <input type="checkbox"/> | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|---|--|-------|-----------|
| ID: | | Date: | 2/27/2020 |
| Location: | RCA Blvd. from East Park Dr. to Prosperity Farms | | |
| Receiving Body: | | | |
| Description: | Cleaning storm basins | | |
| Weather: | Sunny / cloudy | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves / branches | | |
| Debris: | | | |
| Sediments: | | | |
| Litter: | Paper | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | | | |
| Comments: | Cleared debris from storm basins. (8) | | |
| Recommendations: | | | |
| Inspected By: | Shain / Mark | | |
| Department: | | | |
| Vicinity inspected for indication of illicit discharges: <input type="checkbox"/> | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|---|--|-------|---------------|
| ID: | | Date: | 2 / 27 / 2020 |
| Location: | East Park DR. from Burns RD to RCA Blvd. | | |
| Receiving Body: | | | |
| Description: | Cleaning storm basins | | |
| Weather: | Sunny / cloudy | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves / Branches | | |
| Debris: | | | |
| Sediments: | | | |
| Litter: | Paper | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | | | |
| Comments: | Cleaned debris from storm basins. ^{cleaned} 667 | | |
| Recommendations: | | | |
| Inspected By: | Shawn / merle | | |
| Department: | | | |
| Vicinity inspected for indication of illicit discharges: <input type="checkbox"/> | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|-----------------|--------------------------------------|-------|-----------|
| ID: | 2371 | Date: | 3/27/2020 |
| Location: | Hwy A1A | | |
| Receiving Body: | Medians | | |
| Description: | Cleared Litter + Debris from medians | | |

| | |
|-------------|-----|
| Weather: | N/A |
| Corrosion: | N/A |
| Erosion: | N/A |
| Vegetation: | N/A |
| Debris: | N/A |
| Sediments: | N/A |
| Litter: | Yes |
| Oil/Grease: | N/A |
| Other: | N/A |
| Condition: | N/A |

| | |
|------------------|--|
| Comments: | |
| Recommendations: | |

| | | |
|---------------|----------------------|--|
| Inspected By: | Demetrius Carr | |
| Department: | Streets + Stormwater | |

Vicinity Inspected for indication of illicit discharges:

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|---|---|-------|-----------|
| ID: | | Date: | 2/26/2020 |
| Location: | Riverside DR. from MacArthur Blvd. to North camp. | | |
| Receiving Body: | | | |
| Description: | Cleaning storm basins | | |
| Weather: | Cloudy / sunny | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves / branches | | |
| Debris: | | | |
| Sediments: | | | |
| Litter: | Paper | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | Good | | |
| Comments: | Cleared debris from storm basins (4) ^{Cleared} | | |
| Recommendations: | | | |
| Inspected By: | Shaim - Merle | | |
| Department: | | | |
| Vicinity Inspected for indication of illicit discharges: <input type="checkbox"/> | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|---|---|-------|-----------|
| ID: | | Date: | 2/26/2020 |
| Location: | Lighthouse DR. from AIA to Bagonia ST. | | |
| Receiving Body: | | | |
| Description: | DR. 100 | | |
| Weather: | Sunny / cloudy | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves / branches | | |
| Debris: | | | |
| Sediments: | | | |
| Litter: | Paper | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | Good | | |
| Comments: | Cleaned debris from storm basins ^{cleaned} (2) | | |
| Recommendations: | | | |
| Inspected By: | Shawn - Merle | | |
| Department: | | | |
| Vicinity inspected for indication of illicit discharges: <input type="checkbox"/> | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5-

| | | | |
|---|---|-------|-----------|
| ID: | | Date: | 2/26/2020 |
| Location: | Holley Dr. from military to Lighthouse Dr. | | |
| Receiving Body: | | | |
| Description: | Cleaning storm basins | | |
| Weather: | Sunny / cloudy | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves / branches | | |
| Debris: | | | |
| Sediments: | | | |
| Litter: | Paper | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | Good | | |
| Comments: | Cleaned debris from storm basins (4) ^{clean} | | |
| Recommendations: | | | |
| Inspected By: | Shawn Mente | | |
| Department: | | | |
| Vicinity inspected for indication of illicit discharges: <input type="checkbox"/> | | | |

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|-----------------|-----------------------------------|-------|-----------|
| ID: | | Date: | 2/26/2020 |
| Location: | Iron wood from bins to Holley Dr. | | |
| Receiving Body: | | | |
| Description: | cleaning storm basins | | |

| | |
|-------------|-------------------|
| Weather: | Sunny / cloudy |
| Corrosion: | |
| Erosion: | |
| Vegetation: | Leaves / branches |
| Debris: | |
| Sediments: | |
| Litter: | Paper |
| Oil/Grease: | |
| Other: | |
| Condition: | Good |

| | |
|------------------|---|
| Comments: | Cleaned debris from storm basins (6) ^{cleaned} |
| Recommendations: | |

| | | |
|---------------|---------------|--|
| Inspected By: | Shawn — Merle | |
| Department: | | |

Vicinity inspected for indication of illicit discharges:

City of Palm Beach Gardens
Streets/Stormwater Management NPDES Inspection Form
Catchbasin/Inlet

5

| | | | |
|---|---|-------|-----------|
| ID: | | Date: | 2/26/2020 |
| Location: | Burns Rd. from Military Tr. to Prosperity Rd. | | |
| Receiving Body: | | | |
| Description: | Cleaning storm basins | | |
| Weather: | Sunny / cloudy | | |
| Corrosion: | | | |
| Erosion: | | | |
| Vegetation: | Leaves, Branches | | |
| Debris: | Litter | | |
| Sediments: | | | |
| Litter: | Paper / cups | | |
| Oil/Grease: | | | |
| Other: | | | |
| Condition: | Good | | |
| Comments: | Cleaned debris from storm basins (8) ^{cleaned} | | |
| Recommendations: | | | |
| Inspected By: | Shawn Merle | | |
| Department: | | | |
| Vicinity inspected for indication of illicit discharges: <input type="checkbox"/> | | | |