

2018/19 Illicit Discharge Inspections**Westside**

Location	Inspections	Violations	Maintenance	Documentation
Canal 1	5	None	Mowing	Timesheets
Canal 2	5	None	Mowing	Timesheets
Canal 3	5	None	Mowing	Timesheets
Canal 4	5	None	Mowing	Timesheets
Canal 5	5	None	Mowing	Timesheets
Canal 6	5	None	Mowing	Timesheets
Canal 7	5	None	Mowing	Timesheets
Canal 8	5	None	Mowing	Timesheets
Canal 9	5	None	Mowing	Timesheets
Canal 10	5	None	Mowing	Timesheets
Canal 11	5	None	Mowing	Timesheets
Canal 12	5	None	Mowing	Timesheets
Canal 13	4	None	Mowing	Timesheets
Canal 14	5	None	Mowing	Timesheets
Canal 15	5	None	Mowing	Timesheets
Canal 16	5	None	Mowing	Timesheets
Totals	79			

2018/19 Illicit Discharge Inspections**Eastside**

Location	Inspections	Violations	Maintenance	Documentation
Canal A	3	None	Mowing	Timesheets
Canal B	3	None	Mowing	Timesheets
Canal C	3	None	Mowing	Timesheets
Canal D	4	None	Mowing	Timesheets
Canal E	4	None	Mowing	Timesheets
Canal F	5	None	Mowing	Timesheets
Canal G	5	None	Mowing	Timesheets
Canal H	4	None	Mowing	Timesheets
Canal J	4	None	Mowing	Timesheets
Turnpike	4	None	Mowing	Timesheets
Totals	39			
Overall	118			